Sensirion SHT41



Change the init, it need’s only 1Byte to write with 0xFD



Chane register to read to 0xFD (0X24 is a bad register, it starting the heater of the Sensor)



Change the Humidity calculation, it’s different to the SHT31



Change the address selector. SHT41 has not a pin for the address, but the sensor is available with different address.







## Device Overview

| Products | Details |
|---|---|
| STS40-AD1B | 0.2°C *T* accur., 0x44 I²C addr. |
| STS40-BD1B | 0.2°C *T* accur., 0x45 I²C addr. |
| STS40-CD1B | 0.2°C *T* accur., 0x46 I²C addr. |

Change the handle




Change the name