

NOT FOR COMMERCIAL USE

<https://www.matrixtsl.com>

Launching the compiler...

C:\Program Files (x86)\Flowcode\Common\Compilers\vpi\batch\build.bat "pizero accel" "C:\RPI\"

Building pizero accel

In file included from C:\ProgramData\MatrixTSL\FlowcodeV8\CAL\includes.c:443:0,

from pizero accel.c:843:

C:\ProgramData\MatrixTSL\FlowcodeV8\CAL\RPI\RPI\_CAL\_I2C.c:424:5: error: redefinition of 'fd\_j2c1'

int fd\_j2c1 = -1;

~~~~~

In file included from C:\ProgramData\MatrixTSL\FlowcodeV8\CAL\includes.c:420:0,

from pizero accel.c:843:

C:\ProgramData\MatrixTSL\FlowcodeV8\CAL\RPI\RPI\_CAL\_I2C.c:424:5: note: previous definition of 'fd\_j2c1' was here

int fd\_j2c1 = -1;

~~~~~

Error(s) in build!

C:\Program Files (x86)\Flowcode\Common\Compilers\vpi\batch\build.bat reported error code 1

Autoclose turned off

FINISHED